Annexure D

BUILDING SAFETY CERTIFICATE

No.			Dated: 25/06/2025 3.1.C. Paligunaditya (name of the			
It is certified that	at the existing build	ding .A:U:.	. s. C. Pali	gunadity	.t(nam	e of the
building or premi	ses) atVillagl	- Pali	Post-	Pupadit	La Alm	msa
(Black-Dhan	lader (address) is have	vina block(s)	Floor(s) as por	dotails bolow	.J	1012
		ring block(s)/	r loor(s) as per	details below.		
Detail of Block(s)) in Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in	to the same of					
Block	0)	01				
The building is owned/occupied by A: U: G: 1: C: Paligunadity a (name						
of the Institution) have complied with the Building safety requirements in accordance with National						
Building code Rules, and verified by the officers concerned of Lancation (Name of						
Department/ Govt.) on 2506-2025 (date of inspection) in the						
Ramesh Chandra! (Principal Incharge) name and addresses of the						
Manager/Secretary or his representative) and that the building/premises is fit for occupancy for						
running school with effect from 20.10 for a period of years in accordance						
with rule and subject to compliance of the specific conditions as appended.						
1.						
2.						
3.						
4.						
Issued on 25.0	6 2025 at	RES. Al	mora by			
	hever is not applica			ore than six u	se senarato	shoot for
detail.		J120140		oro than six a	se separate	SHEET IOI
	अवर क्षेत्रकी	J.,	Signat	ure with Seal ·		
Signature with Seal:						
	Dues Dues		Designation :			
	Princip		Name & Addre			
65 Page	Govt. Inter	- COLL	S / Idal C	oo or Departing	one onice:	
	Paligunaditya ((Almora)				

भवन सुरक्षा प्रमाण-पत्र

प्रमाणित किया जाता है कि भवन सुरक्षा प्रमाण—पत्र के अन्तर्गत विकास खण्ड—धौलादेवी में अ०उ०रा०इ०का०, पालीगुणादित्य धौलादेवी, अल्मोड़ा के भवन का स्थलीय एवं भौतिक निरीक्षण सहायक अभियन्ता, ग्रामीण निर्माण विभाग, प्रखण्ड अल्मोड़ा द्वारा किया गया। विधालय भवन 2009—10 में भूकम्प रोधी फ्रेम्ड स्ट्रक्चर में निर्मित हैं। निरीक्षण के आधार पर प्रमाणित किया जाता है कि प्राकृतिक आपदाओं को छोड़कर साधारण परिस्थितियों में अ०उ०रा०इ०का०, पालीगुणादित्य धौलादेवी, अल्मोड़ा का भवन भौतिक स्थिति से सुरक्षित है।

२५ १०६ १२८ संह्यिक अभियेगाता प्रामीण निर्माण विशास प्रामीण निर्माण विशास प्रामीण निर्माण विशास प्रखण्ड-अल्मोड़ा।



अधिशासी अभियन्ता ग्रामीण निर्माण विभाग प्रखण्ड-अल्मोडा